



MG ROVER GROUP



Date as Postmark

Our Ref.: Recall A 169

Mr M. G. ...
...

IMPORTANT - MGF SAFETY RECALL Approximate Production dates September 2000 to September 2001

Dear Customer,

MGF REGISTRATION NUMBER. Y...

VEHICLE IDENTIFICATION NUMBER (VIN). SARRDWBGB1D52...

MG Rover Group has identified a concern associated with a small section of the wiring harness fitted to a limited number of vehicles within the MGF range.

Reports have been received that identify it is possible for the seat belt pre-tensioner units to activate unnecessarily when the ignition is switched on. Should this occur, the seat belts will still function as conventional restraints but in the event of a severe frontal impact, the pre-tensioners will no longer be able to automatically reduce any slack in the seat belts.

Your MGF, details of which are confirmed above is within the range of affected vehicles and must have the wiring harness examined and an additional sleeve fitted at the earliest opportunity, to satisfy the requirements of this safety recall notice.

Would you therefore please contact your franchised MG Rover dealer to make arrangements for the necessary work to be carried out. The examination and modification will be carried out free of charge and the dealer will require the vehicle for between three and four hours. This work can only be carried out at an MG Rover franchised dealer using genuine MG Rover parts.

If you no longer own the vehicle, we would be grateful if you could complete the 'Change of Ownership' section attached to this letter and return to MG Rover Group Ltd in the enclosed 'Freepost' envelope. This will enable us to contact the new owner.

MG Rover Group Ltd, PO Box 41, Longbridge, Birmingham B31 2TB, England. Telephone +44 (0) 121 475 2101 Fax +44 (0) 121 482 2403
Registered Office: International Headquarters, Longbridge, Birmingham B31 2TB. Registered in England, Number 1595268. An ISO 9000: 1994 and ISO 14001: 1998 Registered Company.

